OpsIntuition

Sample service report

Job	Sample rooftop unit service
Location	Northside Commons, Suite 204
Lead	Mike
Completed	10:35 AM

Work completed

Replaced the loaded filter, verified airflow, and confirmed the unit is cooling.

Closeout photos



Loaded and replacement filters



Replacement filter seated in its rails